A 01219 03

027 173645

DATE IN SUPPORT OF MISSION. (5) NO AUXILIARY SAR EQUIPMENT WAS USED THIS DATE IN SUPPORT OF MISSION.

BT #8950 NNNN

> DELARTMENT OF DEFENSE NATIONAL MILITARY COMMAND CENTER MESSAGE CENTER

> > 57524

VZCZCMAY143ILN124 MULT ACTION J3(08) DISTR CJCS! (84) CJCS NMCC SECDEF(07) SECDEF: DIA:
CSA HASH DC CNO WASH DC CMC DIA(20) CIA NAIPS(01) FILE(1) (041)

ADV DISTR NMCC 7. THANSIT/271510Z/271530Z/000120TOR0271526 ELASH DE RUMOREA #8958 0271522 Z O 271510Z JAN 73 FM 5680W NAKHON PAHNOM RTAFB THAI

TO AIG 7937 INFO RHMFHTA/COMUSHACTHAI/J=31 RUMOSRA/US CONSOLATE/UDORN THAT (OCCURING IN THATLAND) RUWTEJA/HQ USAFSS/DOC/KELLY AFB TEX RUEADWS/DIRECTOR/NSA/FT GEORGE G MEADE/MD BT

HACY CC/027/5680W DUC/OPREP-3 PINNACLE/008 H. COMBAT LOSS - NAIL 89-0V-10 CPREP=3 VOICE 27/0933Z/JAN 73 H1. OPREP-3 PINNACLE 27/0945Z/JAN 73 LOSREP 27/1155Z/JAN 73 H2. 27/0920Z/ JAN/73 H3, NA H4. IMMEDIATELY AFTER TAPROOM 113, AN F=4, WAS DOWNED BY ENEMY GROUND FIRE, NAIL 89, OV-10, ACFT NBR 68-380F MOVED INTO THE AREA TO CONTROL THE SAR MISSION. AS NAIL BO FLEW OVER THE VILLAGE WHERE THE TWO F-4 CREHMEN HAD LANDED, AN SA-7 MISSILE WAS FIRED AT THE AIRCRAFT.

THE HISSILE HIT NAIL 89 IN THE RIGHT SIDE CAUSING THE AIRCRAFT TO GO INTO A SPIN. BOTH CREWMEN EJECTED AND GOT GOOD CHUTES. VUICE CONTACT WAS EXTABLISHED WITH ONE CREWMEMBER BUT NO ONE CAN CONFIRM WHETHER IT WAS THE ALPHA OR BRAVO MAN. HE STATED THAT HE WAS BEING CAPTURED. NO FURTHER CONTACT WAS MADE. ELECTRONIC SURVIELANCE IS CONTINUING. APPROX POSITION IS 3:3DEG/40NM CHANNEL 69. (HUE)

PAGE 1

00101001

IMMEDIATE

DEPT. ATMENT OF DEFENSE NATIONAL MILITARY COMMAND CENTER

MESSAGE CENTER

C. AIRCRAFT IDENTIFICATION (1) MODEL/DESIGN/BERIES! UV=1MA (2) ACFT SERIAL NUMBER: 68-3806 (3) MISSION NUMBER: 7745 (4) CALL SIGN: NAIL 89 NUMBER 1 IN A FLT OF UNE (b) OPERATIONAL BASET NKP RTAFB (6) AIRCRAFT ASSIGNMENT: PACAF: 13AF/56SUH/23TASS (7) UNIT IDENTIFICATION CODE (UIC) NARMIG D. TIME/LUCATION OF LOSS! (1) TIME OF HITE 27/0920Z JAN 73 AT 16 54N/10712E (2) TIME DOWN/LOST 270920Z JAN 73 AT 16 54N/10712E AN ITOT (E) E AIRCREW IDENTIFICATION/STATUSE (1) NAMES MARK A. PETERSON POSITION FP (2) GRADE 1LT (3) SN 268 44 7199FR GIVE SUFFIX) (A) ORGANIZATION123TASS (5) STATION NKP RTAFB (6) STATUS: 7, ((7) NUMBER MONTHS IN COMBAT ZONE 4. NUMBER COMBAT MISSIONS 51 (1) NAME: GEORGE W. MORRIS POSITION: CP (2) GRADES CAPT (3) 8N DATA (4) ORGANIZATION: 23TASS (5) STATION NKP RTAFB (6) STATUS? UNK (7) NUMBER MONTHS IN COMBAT ZONE 3 NUMBER COMBAT MISSIONS 22 F. MISSION/TARGET INFORMATION: (1) TYPE MISSION: VR (STATE IF CAS, STRIKE, ETC.) (2) TYPE TARGET! NA FAC CONTROLLED! NA FAC CALL SIGNE NA (3) TARGET LOCATION BY LATITUDE/LONGITUDE: NA (4) TARBET WEATHER: DAY - UNK

PAGE 2

09011111

57326

DEFA MENT OF DEFENSE

NATIONAL MILITARY COMMAND CENTER

MESSAGE CENTER

57326

(9) WEAPONS CARRIED WHEN HIT UNK

(10) DISPOSITION OF ORDANCE DELIVERED ON TGT WAS

N/A

TYPE ORD BEING DELIVERED WHEN HITE N/A

C11; RELEVANT COMMUNICATIONS FROM CREW MEMBERS NOT RECOVERED: SEE RMKS
H. RESCUE INFORMATION:

(1) CHUTE DESERVED: YES- BEEPER SIGNAL: - NO VOICE CONTACT ESTABLISHED: YES- (2) ENVIRONMENT AT RESCUE SITE; COASTAL AREA WITH

ENEMY ACTIVITY.
(3) AGENCY DIRECTING SAR! JACK
(4) EXTENT OF SAR EFFORT: UNK

(5) RECOVERY WAS MADE AT NA Z BY NA
(6) WHEN AND WHY SAR WAS TEMINATED: IN

PROGRESS

I. REMARKS: NAIL 89 WAS DIVERTED

FOR F-4 SAR TAPROUN 113. POSSIBLY

HIT BY SA-7. TWO GOOD CHWTES REPORTED.

BRIEF CONTACT WITH N-89 INDICATING HE WAS

ABOUT TO BE CAPTURED. UNCERTAIN AT THIS

TIME WHETHER "A" OR "B" CRWMEMBER

WAS ABOUT TO BE CAPTURED.

H0932 ANNOTES DRC 590

3

NNNN 271257Z 00011111

21

7 \$